Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2	"5485127".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:14
L2	. 2	"5737616".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:14
L3	2	"5778237".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:14
L4		"5913068".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR .	OFF	2006/04/21 16:15
L5	3	"5996084".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:15
L6	2	"6167524".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:15
L7	2	"5338265".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:16
L8	2	"6182232".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:16
L9	2	"6260151".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:16

L10	2	"6415388".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:16
L11	10	(US-5485127-\$ or US-5737616-\$ or US-5778237-\$ or US-5913068-\$ or US-5996084-\$ or US-6167524-\$ or US-5338265-\$ or US-6182232-\$ or US-6260151-\$ or US-6415388-\$). did.	USPAT	OR	OFF	2006/04/21 16:17
L12	210	((power near2 (monitor\$3)) and sensor\$1 and (demand or load)). clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR .	OFF	2006/04/21 16:47
L13	0	11 and 12	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:45
L14	1008	((power near2 (monitor\$3)) and sensor\$1).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:46
L15	1	11 and 14	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:47
L16	1523	((power near2 (monitor\$3 or control\$4)) and sensor\$1 and (demand or load)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:47
L17	0	11 and 16	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:48
L18	8920	((power near2 (monitor\$3 or control\$4)) and sensor\$1).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:48

		LAST Searc	sco. y			
L19		11 and 18	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:48
L20	10069	((power near2 (monitor\$3 or control\$4 or regulat\$3 or adjust\$5)) and sensor\$1).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:49
L21	1	11 and 20	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 16:49
L22	16958	((power near2 (monitor\$3 or control\$4 or regulat\$3 or adjust\$5)) and sens\$3).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 17:04
L23	3	11 and 22	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF .	2006/04/21 16:50
.L24	2	23 and (demand or load\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 17:03
L25	1	23 and resource\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 17:04
L26	4812	((power near2 (monitor\$3 or control\$4 or regulat\$3 or adjust\$5)) and sens\$3 and (demand\$3 or load\$3 or utiliz\$5)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF ·	2006/04/21 17:08
L27	0	26 and 11	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 17:06
L28		(HEPNER and DAVID and F).in.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 17:08

			T		T <u> </u>	
L29	1	28 and 26	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 17:10
L30	15	(WALLS and ANDREW and DALE).in.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 17:09
L31	1	30 and 26	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 17:10
L32	109341	((International and Business and Machines) or IBM).as.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 17:12
L33	36	26 and 32	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 17:13
L34		33 and ((first or second) adj sensor\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 17:16
L35	1	33 and ((first or second) adj (device\$1 or module\$1 or unit\$1 or circuit\$1))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/21 17:17